


GrainPro® Hermetic Bag Premium™



(TWIST & TIE)




1 Fold GrainPro Hermetic Bag Premium lengthwise and place inside the outer bag. Outer bag should be smaller than the GrainPro Bag.



2 Unfold GrainPro Hermetic Bag Premium and roll extra plastic to prevent damage.




3 Pour the commodity. Leave 40 cm of plastic for proper sealing.




4 Unroll and remove air by pressing down on the commodity.

OPTIONAL: Add oxygen absorber to immediately lower the oxygen level.

In case of pulses, oxygen absorbers are to be added (1 sachet per 50 kg commodity)




5 Twist the extra plastic tightly. Tightly fasten reusable cable tie or rope




6 Fold the twisted plastic and lock with another cable tie or rope.


OPTIONAL: a cable-tie gun can be used




7 Close the outer bag by tying or sewing at 3cm distance from the "tied" inner liner.



8 Stick the 'No Hooks' label on the outer bag.



9 After using, clean, dry and fold undamaged GrainPro Hermetic Bag Premium, and save the reusable cable tie for future use.



Sufficiently low permeation against gases, moisture and water.



No need to use fumigants.



For more Information about hermetic storage systems, visit www.grainpro.com or email customer@grainpro.com